

MARION COUNTY SURVEYOR'S OFFICE


SECTION CORNER RECORD

DEBRA S. JENKINS
MARION COUNTY SURVEYOR

SEC. 35 TWN. 15_N RNG. 2_E

BRYAN F. CATLIN, PLS
TECHNICAL SUPERVISOR

Date: 5-21-09
Party Chief: Wilcoxen
Crew: Taylor / Finney
Type of Marker: Airport disk in steel box
Method of Establishment: County: 5-29-98
IN S.P.C. E Zone, NAD 83
Name: 15023508
N: 493 417.318 0(m)
E: 47 490.764 0(m)



Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 36" white oak bearing S 72 E 30 links and a 10" beech bearing N 72 W 20 links.(Marion County Atlas p. 2) A survey by D.B. Hasbrook on March 19,1855 indicates no stone or witnesses. (Decatur Legal Book p. 6) Corner referenced by MCS on 12/23/1947 and called an axle set. Corner referenced by Monroe on 10/18/60 and called an auto axle. Corner referenced by McLand on 2/18/71 and called a metal monument with ringed center. Corner referenced by McLand on 3/21/75 and called an axle. Corner referenced by Greene on 10/10/86 and called a RR spike over stone 4"down. Corner referenced by Wilcoxen on 3/13/92 and called an axle 6" down. Corner referenced by Wilcoxen on 5/29/1998 and called an airport authority disk in steel box. Corner referenced by Wilcoxen on 6/14/2003 and called an airport authority disk in steel box. Corner referenced by Wilcoxen on 5/21/09 and called an airport authority disk in steel box.

REF.	DISTANCE	DESCRIPTION
1.	42.35'	Top nut of fire hydrant
2.	101.77'	NW corner of foundation 6744 Thompson Rd
3.	64.22'	SW corner of porch 6744 Thompson
4.	80.67'	SE corner of porch 6744 Thompson
5.	23.07'	PK nail NW PwP #62-683 18" up
6.	30.65'	PK nail w/shiner NE 24" walnut 18" up
7.	22.67'	Due W to NQ 2-14-2 (RR spike)